
Certificate of Test Conformance Number: 103694 Issue 1

Customer Name & Address: Lazer Lamps
Units 1 & 2
Harlow Mill Business Centre
Essex
CM20 2FD

Customer Order Number: 0859

Test Item(s) Receipt Date: 18th July 2019

Test Item(s) Description: Heavy Duty Work Lamp

Test Item(s) Part Number(s): Utility 25

Test Item(s) Serial Number(s): #1 & #2

Test Item(s) Quantity: 2

Reference Standard(s): DIN 40 050 Part 9: Road Vehicle Degrees of Protection

Applied Test(s): IP6Kx, IPx9K

Test Date(s): 18th to 23rd July 2019

Test Results: The detailed tests were performed in accordance with the requirements of the defined environmental test standards.

Lamp #1 was subjected to the IPx9K water test.

Lamp #2 was subjected to the IP6Kx dust test.

On completion of the tests, no water or dust ingress was observed within the enclosures.

Therefore, Lamp #1 conformed to the requirements of the IPx9K rating and Lamp #2 conformed to the requirements of the IP6Kx rating.

Author:



Paul Lee
Test Lab Manager

Approval:



Steve Drane
Service Manager

Issue Date:

24th July 2019

The results detailed herein relate only to the test item(s) submitted for testing.